

# DIGITAL PRESSURE METER

Reference : PRESSIO



Digital display pressure meter and analog output  
Technical characteristics:

- Display: backlit LCD display
- Measurement range: 0 to 4000 hPa
- Unit: hPa or mbar (choice by push button)
- Analog output on banana sockets  $\varnothing$  4 mm safety: 0 to 4 V (1mV / hPa)
- A button is used to select an absolute or relative pressure measurement.
- Power supply: 5V / 1A mains unit or 9V type 6F22 battery (not included)
- Dimensions: 110 x 65 x 30 mm