

STERILITY INDICATOR TAPE

Reference : RIS



Steam indicator tape:

This tape has white streaks that turn black when Sterilization is complete:

3 min at 134° C or 15 minutes at 121° C

19 mm x 50m