

ABSOLUTE PRESSURE / TEMPERATURE

Reference : PS-2146



This sensor makes it possible to simultaneously or independently measure the absolute pressure and the temperature. It is supplied with a temperature sensor and a small hose and tips to connect it to the pressure sensor.

Technical characteristics:

- Measurement ranges:
- From 0 to 700 kPa for pressure
- From -10 ° C to +70 ° C for the temperature
- Precision: 2 kPa and 0.5 ° C
- Units: kPa, N / m², atm, psi (pressure) and ° C, K, ° F (temperature)
- Sampling frequency: up to 100 Hz